

Message

From: Wagner, Christine [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=12068C1889924ECF96F692831F0C77D4-CWAGNE02]
Sent: 1/30/2020 6:46:38 PM
To: [Nonresponsive based on revised scope]
CC: [Nonresponsive based on revised scope]
Subject: Fwd: Shiloh Church[3082585]
Attachments: 3082585_935725_fr.PDF; ATT00001.htm

[Nonresponsive based on revised scope]

Looks like some of Property #2 is Area 2 material (RCRA) at a minimum. Hopefully the PCB results do not kick it over to treatment

We will have to enter this into Scribe but no rush
Thanks
Chris

Begin forwarded message:

From: [Nonresponsive based on revised scope]
Date: January 30, 2020 at 1:16:58 PM EST
To: "Wagner, Christine" <Wagner.Christine@epa.gov>, [Nonresponsive based on revised scope]
[Nonresponsive based on revised scope]
Subject: FW: Shiloh Church[3082585]

Soil results

Sent from my Verizon, Samsung Galaxy smartphone

----- Original message -----

From: [Nonresponsive based on revised scope]
Date: 1/30/20 11:34 (GMT-05:00)
To: [Nonresponsive based on revised scope]
Subject: Shiloh Church[3082585]

The following reports are attached:

WO 3082585 , Work ID Shiloh Church []

--- End Of List ---

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any

dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.